



2-22-08

lfr

DAC

PATENT
Customer No. 22,852
FHFGD Ref. No. 9145.0021-00

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:)
TZONG-KWANG HENRY YEH et al.) Group Art Unit: 2189
Application No.: 10/808,253) Examiner: FLOURNOY, Horace L.
Filed: March 23, 2004)
For: COLLISION DETECTION IN A) Confirmation No.: 4222
MULTI-PORT MEMORY SYSTEM)

MAIL STOP PETITION

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

PETITION FOR REVIVAL OF AN APPLICATION FOR PATENT
ABANDONED UNINTENTIONALLY UNDER 37 CFR 1.137(b)

The above-identified application became abandoned for failure to submit corrected drawings as indicated in the Notice of Allowance and Fee(s) Due and Notice of Allowability mailed on May 1, 2007, which set a three-month period for response. Although Applicants paid the issue fee set forth in the Notice of Allowance and Fee(s) Due, the application effectively became abandoned on August 2, 2007, by Applicants' failure to provided corrected drawings, as was required by the Notice of Allowability. Applicants had been informed by the Examiner that replacement drawings were not needed and therefore did not submit them. The entire delay in filing the required reply from the due date for the required reply until the filing of a grantable petition under 37 C.F.R. § 1.137(b) was unintentional.

Applicants hereby petition for revival of this application. Please charge the petition fee of \$1,500.00 to Deposit Account No. 06-0916.

In addition, Applicants submit herewith corrected drawings which comply with the requirements set forth in the Notice of Allowability.


If there are any other fees due in connection with the filing of this response, including any fees required for an extension of time under 37 CFR § 1.136, such an extension is requested, and the Commissioner is authorized to charge any related fees to Deposit Account 06-0916.

Respectfully submitted,

FINNEGAN, HENDERSON, FARABOW,
GARRETT & DUNNER, L.L.P.

Date: February 20, 2008

By:



Gary J. Edwards
Reg. No. 41,008
(650) 849-6622

Attached: Five (5) drawing Replacement Sheets corresponding to Figs. 1A-1B, and 2-4

EXPRESS MAIL LABEL NO.
EM 074697371 US